

**2008 Airbus  
EC-135T2+**


#630

F-HTPI



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc © 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.

**PRELIMINARY  
SPECIFICATIONS**

# 2008 Airbus EC-135T2+

## #630 | F-HTPI



### TOTAL HOURS

6,633 hours since new

**LANDINGS: 21,582**

### ENGINES

Two Safran Arrius 2B2 engines

| # | S/N   | TSN   | N1 Cycles | PT Cycles |
|---|-------|-------|-----------|-----------|
| 1 | 32355 | 7,544 | 6,326     | 18,262    |
| 2 | 32204 | 6,202 | 7,674     | 19,863    |

### HIGHLIGHTS

Single & Dual Pilot IFR

Aerolite EMS Kit

Airbus service center maintained

Located : Albertville, France

### AVIONICS

SMD45 MEGHAS Glass cockpit  
 Auto Pilot APM2000 (DAFCS)  
 Mission Audio panels ICS BECKER AS3100-12  
 DME DM-441B transreceiver,  
 ADF DF-431B Chelton receiver  
 Radar Altimeter RCVR/XMTR KRA 405B  
 Mode S transponder MST-67A  
 Trimble 2101 GPS receiver  
 Stand By Horizon

### OTHER FEATURES

ELT Artex C406-NHM  
 Air Conditioning  
 BrightSaver 2 flight data recorder  
 Satellite Tracking & Data Transmission System  
 Strobe lights

### GEAR BOX & ENGINE OVERHAUL

| Designation                 | P/N          | TBO   | Rem. Hrs | %Rem. |
|-----------------------------|--------------|-------|----------|-------|
| Main Gear Box               | 4649020010   | 5,000 | 2,150    | 43%   |
| Tail Gear Box               | L652A0101052 | 5,000 | 3,071    | 61%   |
| <b>ARRIUS 2B2 L/H 32355</b> |              |       |          |       |
| Module 1                    | 70EM017020   | 4,000 | 1,150    | 28%   |
| Module 2                    | 70EM027070   | 4,000 | 1,150    | 28%   |
| <b>ARRIUS 2B2 R/H 32204</b> |              |       |          |       |
| Module 1                    | 70EM017020   | 4,000 | 1,150    | 28%   |
| Module 2                    | 70EM027070   | 4,000 | 3,537    | 88%   |

Specifications updated January 18<sup>th</sup>, 2025 - Medical loose equipment not included

### CONTACT

**Emmanuel Dupuy** / ed@aeroasset.com

**+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.


**PRELIMINARY  
SPECIFICATIONS**

**2008 Airbus EC-135T2+**  
#630 | F-HTPI



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.

**PRELIMINARY  
SPECIFICATIONS**

**2008 Airbus EC-135T2+**  
#630 | F-HTPI



CONTACT  
**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)  
**+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.


**PRELIMINARY  
SPECIFICATIONS**

**2008 Airbus EC-135T2+**  
#630 | F-HTPI



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.


**PRELIMINARY  
SPECIFICATIONS**

**2008 Airbus EC-135T2+**  
#630 | F-HTPI



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.


**PRELIMINARY  
SPECIFICATIONS**

**2008 Airbus EC-135T2+**  
#630 | F-HTPI



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.


**PRELIMINARY  
SPECIFICATIONS**

**2008 Airbus EC-135T2+**  
#630 | F-HTPI



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.

**PRELIMINARY  
SPECIFICATIONS**




2008 Airbus EC-135T2+

#630 | F-HTPI



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.


**PRELIMINARY  
SPECIFICATIONS**

**2008 Airbus EC-135T2+**  
#630 | F-HTPI



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.


**PRELIMINARY  
SPECIFICATIONS**

**2008 Airbus EC-135T2+**  
#630 | F-HTPI



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.


**PRELIMINARY  
SPECIFICATIONS**

**2008 Airbus EC-135T2+**  
#630 | F-HTPI



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.

**PRELIMINARY  
SPECIFICATIONS**


2008 Airbus EC-135T2+  
#630 | F-HTPI

 **AEROASSET**



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.


**PRELIMINARY  
SPECIFICATIONS**

2008 Airbus EC-135T2+  
#630 | F-HTPI



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.


**PRELIMINARY  
SPECIFICATIONS**

2008 Airbus EC-135T2+  
#630 | F-HTPI



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.


**PRELIMINARY  
SPECIFICATIONS**

2008 Airbus EC-135T2+  
#630 | F-HTPI



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.

**PRELIMINARY  
SPECIFICATIONS**



2008 Airbus EC-135T2+  
#630 | F-HTPI

**AEROASSET**



CONTACT


**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

**+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.


**PRELIMINARY  
SPECIFICATIONS**

2008 Airbus EC-135T2+  
#630 | F-HTPI

 **AEROASSET**

CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.


**PRELIMINARY  
SPECIFICATIONS**

2008 Airbus EC-135T2+  
#630 | F-HTPI



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.

**PRELIMINARY  
SPECIFICATIONS**


2008 Airbus EC-135T2+  
#630 | F-HTPI

 **AEROASSET**



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc © 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.

**PRELIMINARY  
SPECIFICATIONS**

2008 Airbus EC-135T2+  
#630 | F-HTPI



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

**+1 (289) 400-4725**

© Copyright - AeroAsset, Inc © 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.


**PRELIMINARY  
SPECIFICATIONS**

2008 Airbus EC-135T2+  
#630 | F-HTPI



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.


**PRELIMINARY  
SPECIFICATIONS**

2008 Airbus EC-135T2+  
#630 | F-HTPI



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.


**PRELIMINARY  
SPECIFICATIONS**

2008 Airbus EC-135T2+  
#630 | F-HTPI



CONTACT

**Emmanuel Dupuy** / [ed@aeroasset.com](mailto:ed@aeroasset.com)

 **+1 (289) 400-4725**

© Copyright - AeroAsset, Inc ® 2025 - All Rights Reserved -Specifications Subject To Verification upon Inspection.

**PRELIMINARY  
SPECIFICATIONS**





**AEROASSET.COM**

181 Bay Street, Toronto,  
ON, M5J 2T9, Canada  
Phone: +1 732 578 8217  
sales@aeroasset.com



© Copyright - AeroAsset, Inc © 2025 - All Rights Reserved  
Specifications Subject To Verification upon Inspection.

